Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

Cisco Wireless LAN Controller Models

Access Points and Mobility Services Engine

Table 5

Open Caveats

Bug ID	Headline
CSCuo75037	High Priority Access Point Keeps Flapping when License Count is Exceeded
CSCuu13106	Traffic not recovered over cts link after hot swap of uplink

Resolved Caveats in Cisco IOS XE Release 3.7.4E